## IN THE SPECIFICATION

Please replace the paragraph beginning on column 5, line 1 and ending on column 5, line 9 with the follows:

However, the insulator [140] 14 surrounding the central conductor 130 is replaced by an insulating coating 140, while the shield 15 is replaced by a conductor coating 150 and the insulator 16 by an insulator coating 160. As for the embodiment of FIG. 3, the conductor coating 150 and insulator coating 160 have been removed from a portion of the distal end of tip 170. Also, the proximal end (not shown) of this coaxial cable is adapted to connection to the standard antenna input of control station 12 (FIG. 1).